

FITNESS CERTIFICATE 2025- 26 (Assistant Engineer / Assistant Executive Engineer)		
Name of School		THE WHITE SCHOOL
1	Name of Officer	Thushara.PR
2	Location	Perumanna
3	Period for which the certificate is issued	2025-26
4	Types of building	Permanent RCC building 7.97m x 8.97m x 3.90m - 12 Classes GF 7.97m x 8.97m x 3.90m - 12 Classes 1st basement 7.97m x 8.97m x 3.90m - 12 Classes 2nd basement (The above building have sufficient number of toilets, passages and other facilities
5	Nature of defect if any	
	a Foundation and basement	Nil
	b Superstructure	Nil
	c Doors and windows	Nil
	d Wood work wrought up	Nil
	e Roof	Nil
	f flooring	Nil
	g miscellaneous (cracks if any)	No visible cracks found
6	Any major defects noticed which will render the building unsafe in any manner	Nil
7	Whether maintenance work have been done properly	Yes
8	Whether the structure is sound or not for conducting classes	Sound for conducting classes under normal wind and Weather condition
Note	1	The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
	2	Any additional observation deemed necessary for the necessary for the certificate, may be furnished separately with the Certificate
Certified that the school was inspected by me on 16/06/2025 and found to be Fit to conduct classes for the period for the stated above		

Place: Perumanna
Date : 16/06/2025



Assistant Engineer


16/6
Assistant Engineer

L.S.

Erumangudi Panchayath

FITNESS CERTIFICATE 2025- 26 (Assistant Engineer/ Assistant Executive Engineer)		
Name of School		THE WHITE SCHOOL
1	Name of Officer	Thushara.PR
2	Location	Perumanna
3	Period for which the certificate is issued	2025-26
4	Types of building	Permanent Sheet Roof Single Storied (1308.61m2) 8.00m x 6.00m x 3.60m - 18 Classes
5	Nature of defect if any	
	a Foundation and basement	Nil
	b Superstructure	Nil
	c Doors and windows	Nil
	d Wood work wrought up	Nil
	e Roof	Nil
	f flooring	Nil
	g miscellaneous (cracks if any)	No visible cracks found
6	Any major defects noticed which will render the building unsafe in any manner	Nil
7	Whether maintenance work have been done properly	Yes
8	Whether the structure is sound or not for conducting classes	Sound for conducting classes under normal wind and Weather condition
Note	1	The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
	2	Any additional observation deemed necessary for the necessary for the certificate, may be furnished separately with the Certificate
Certified that the school was inspected by me on 29/05/2025 and found to be Fit to conduct classes for the period for the stated above		

Place: Perumanna
Date : 29/05/2025



Assistant Engineer
Perumanna Grama Panchayat